

FIG. 1






FIG. 3(a)




FIG. 3(b)




FIG. 3(c)




FIG. 3(d)





FIG. 3(e)



SIMULTANEOUS PUNCHING·LAMINATING

FIG. 4(a)

FIG. 4(a)




FIG. 4(b)





FIG. 4(c)



POLARIZING

FIG. 4(d)





FIG. 4(e)



LAMINATION AFTER PUNCHING

FIG. 5(a)




FIG. 5(b)




FIG. 6(a)




FIG. 6(b)




FIG. 6(c)




FIG. 6(d)




FIG. 6(e)




FIG. 7




FIG. 8(a) FIG. 8(b) FIG. 8(c) FIG. 8(d) FIG. 8(e)

FIG. 8(a)




FIG. 8(b)




FIG. 8(c)




FIG. 8(d)

DICING STEP

FIG. 8(e)






FIG. 9(a)




FIG. 9(b)




FIG. 10(a)




FIG. 10(b)




FIG. 11




FIG. 12




FIG. 13(a)




FIG. 13(b)




FIG. 14




FIG. 15

